

**USEPA REGION III ENFORCEMENT AND COMPLIANCE ASSURANCE DIVISION
NON-HAZWOPER SAFETY CHECKLIST**

Facility Name	Hanover Foods Corp		
Facility Street Address	1550 York Street		
Facility City, State & Zip Code	Hanover	PA	17331
Facility Contact Name/Phone #	EPA contractor will contact facility operator		
EPA Inspector	Amanda Pruzinsky Shane McAleer	NAICS Code (SIC Code)	
Other EPA Personnel			
Inspection Date	February 4, 2021	Case Number	N/A

Site Type: Check all that apply:

- | | |
|--|---------------------------------------|
| <input checked="" type="checkbox"/> Active | <input type="checkbox"/> Inactive |
| <input checked="" type="checkbox"/> Controlled | <input type="checkbox"/> Uncontrolled |
| <input type="checkbox"/> Residential | <input type="checkbox"/> Industrial |

Special Site Hazards:

Please use this links to identify risk associated with COVID in the area you intend to inspect:

Interim H&S Guidelines: [COVID-19 Health & Safety Guidelines for Field Activities](#).

According to the CDC website, York County has experienced a total of 26,813 COVID-19 cases and 630 total deaths attributed to COVID-19. On 1/28/2021, the CDC website shows that in the last 7-days, York County has experienced 342.49 average daily cases per 100,000 people. Inspectors will bring their own PPE including face masks, wipes, and gloves.

Applicable Safe Work Practices (SWP): (Check as many as applicable to the Site)

- | | |
|---|---|
| <input checked="" type="checkbox"/> General Safe Work Practices
<input type="checkbox"/> Lockout/Tagout Procedures
<input type="checkbox"/> Hot Work Practices
<input type="checkbox"/> Safe Electrical Work Practices
<input type="checkbox"/> Fall Protection Practices
<input type="checkbox"/> Portable Ladder Safety
<input type="checkbox"/> Drum and Container Handling Practices
<input type="checkbox"/> Flammable Hazards and Ignition Sources
<input type="checkbox"/> Heat Stress
<input type="checkbox"/> Cold Stress
<input type="checkbox"/> Corrosives
<input type="checkbox"/> Poison and Toxic Materials
<input type="checkbox"/> Oxidizers
<input type="checkbox"/> Transportation Shipping Papers
<input type="checkbox"/> Pressurized Containers | <input type="checkbox"/> Radiation Safety Practices
<input type="checkbox"/> Permit-Required Confined Space
<input type="checkbox"/> Non-Permit-Required Confined Space
<input type="checkbox"/> Oil and Petroleum Distillate Fuel Hazards
<input type="checkbox"/> Safe Work Practices with Air Purifying Respirators
<input type="checkbox"/> Safe Work Practice for UXO Work
<input checked="" type="checkbox"/> Biohazards (e.g. COVID)
<input type="checkbox"/> Underground Storage Tanks
<input type="checkbox"/> Working Safely with Hydrazine
<input type="checkbox"/> Working Safely with Benzene
<input type="checkbox"/> Working Safely with Ammonia
<input type="checkbox"/> Working Safely with Chlorine
<input type="checkbox"/> Slip, Trip and Fall Hazards
<input type="checkbox"/> Other: |
|---|---|

Initial Site Information/Chemicals:

During the site visit, EPA will conduct a site inspection of industrial wastewater facilities Hanover Foods Corp on February 4, 2021, which receives wastewater from canning operations as well as noncontact cooling water. It is not expected that EPA personnel will come into direct contact with any chemicals.

Level of Protection – Evaluate and describe and justify the need for respiratory protection due to COVID, if applicable:

EPA personnel will not be wearing respirators for this site visit. Participants will bring their own gloves, face masks or coverings, and disinfectant wipes. Furthermore, EPA personnel will wear PPE for construction site visits included protective footwear (approved boots), hardhats, safety glasses, and reflective vests as needed.

<input type="checkbox"/> A	<input type="checkbox"/> B	<input type="checkbox"/> Respiratory	<input type="checkbox"/> Protective Clothing	<input checked="" type="checkbox"/> Head and Eye
<input type="checkbox"/> C	<input checked="" type="checkbox"/> D	<input checked="" type="checkbox"/> Gloves	<input type="checkbox"/> First Aid Equipment	<input checked="" type="checkbox"/> Boots
		<input type="checkbox"/> Face Shield	<input checked="" type="checkbox"/> Disposable surgical mask	<input checked="" type="checkbox"/> Cloth covering or mask

Specific PPE required by facility - Please contact the facility to identify PPE requirements:

Inspectors needs to determine if the facility can provide **virtual connection and/or social distancing (6ft) consistently**

No additional PPE is required by the facility. All attempts will be made to limit the number of individuals on-site for compliance monitoring, ensure social distancing, limit or eliminate all indoor components of the inspection, and wear covid-19 PPE such as masks and glasses.

☒ I am **NOT** voluntarily using an my own N95 respirator while in the field

☐ I am voluntarily using my own N95 respirator while in the field, and certify that I have fulfilled the following requirements:

☐ completed Online training N95 Voluntary Use training

☐ received R3 SHEM approval kane.rachael@epa.gov

Emergency Contacts:

Fire Department: Use 911

Police Department: Use 911

ECAD Staff:

Lead Inspector: Amanda Pruzinsky

Secondary Inspectors: Shane McAleer

Hospital Route Map (attach)

The nearest hospital is open 24 hours and is about 2.4-2.8 miles away about a 6-8-minute drive from the inspection site location depending on the route taken (see map attached).

Hospital Name:

UPMC South Central PA

Hospital Address:

300 Highland Ave, Hanover, PA 17331

Other EPA Personnel (if applicable) :

Inspector Signature(s):

Pruzinsky,
Amanda

Digitally signed by
Pruzinsky, Amanda
Date: 2021.01.28
13:45:23 -05'00'

Shane
McAleer

Digitally signed by Shane
McAleer
Date: 2021.01.28
15:45:37 -05'00'

Supervisor's Signature:

STACIE
PRATT

Digitally signed by
STACIE PRATT
Date: 2021.01.28
17:43:23 -05'00'

